


ST-1 - Wiring Diagram Complete

Suitable for: ST-1, ST-1L and ST-1M



- Includes wires pre soldered at factory
- Purple wires may not be required if cavities are shielded and Pots are in contact with the shielding.
- Solder point

wire to

tip

Output Jack