
## Pit Bull JZ-6 - Wiring Diagram User Wiring



Solder point

the shielding.