




## HB-4- Wiring Diagram Kit requirements

Suits: HB-4 and HB-4S

"Hot" wire  
(white)



Output Jack  
(prewired)

 Solder point

Note: wires pre soldered at the factory are not pictured.