


Suitable for: PB-4, PBA-4, PB-4L, VP-4




● Solder point

Notes:

- Wires pre soldered at factory – only shows connections required by user
- **Purple** wires may not be required if cavities are shielded and Pots are in contact with the shielding.

Ground to sleeve



Output Jack

"Hot" wire to tip