



● Solder point

### Notes:

- No wires pre soldered at factory
- Purple wires may not be required if cavities are shielded and Pots are in contact with the shielding.